PEROFORMA FOR THE SAFETY OF SCHOOL BUILDING

PART-1

(To be filled by the Head of School/Institution)

1. Name of the School : DAV Centenary Public School, Ja	graon
2. Location : Sherpura Raod, Jagraon	
3. Plot of Area : 87120 Sq. ft.	0
4. Plinth Area $: \frac{16400}{Gr} + \frac{16400}{Istf} + \frac{435^{\circ}}{2ndf} = \frac{3715^{\circ}}{2715} sq.ft.$	
	ter angli tanin dita ing ti
5. Number of Storey's : Two + one = Triple Storey	
6. Year of construction of the Building : 1987	
7. In the building has been constiunder Constructed under	r the supervision of
the pervasion of the qualified engineer, the following details n	
A) Name of Engineer with Qualification:	
B) Address of the Engineer	
C) Sat of strudical drawing used in the construction, if availabl	e. [Yes, Available]
D) Name and Address of Architect with Qualification: [Kann	av khosla, 568A, Police house,
Civil	lines, dudhiana)
8. Whether the building has been constructed for the purpose:	
A) School	YES/NO
B) Residential purpose and concerted for use as a School	YES/NO
C) Residential purpose and cover for use a building	YES/NO
9. Materials used for roofs	
A) R.C.C.Slabs	YES/NO
B) Cement Mortar	YES/NO
C) Wooden Joints and battons	YES/NO
10. Material used for walls	
A) Mud matter	YES/NO
B) Cement Mortar	YES/NO
C) Plaster (i) Lime Mortar	YES/NO
11. Flooring	
A) Conglomerate	YES/NO
B) Terrazzo	YES/NO
C) Brick paving	YES/NO
12. A detailed drawing indicating dimension of the rooms alongwit	h size and location of doors
and window (attached) Yes	Zabar

Signature with stamp of the Heads of School/Institution

Headmaster DAV Centenary Public School, Jaccord (Distt. Ldh.)

PART-II (To be filled by the SDE of PWD B&R Deptt.)

Name of the School: DAV Centenary Public School, Jagraon

- A. I have visited the above mentioned School on $3 \le 2020$ and have visited by inspection it from all angle of safety and I find it fit for moral use as a school building.
- B. In case any addition/alteration or expansion and modification to this building is to be carried out. The same be carried out under the supervision of a technically qualified Engineer and this certificate may again be taken after the completion from the undersigned.
- C. In case the building is effected by flood or if there is settlement of walls/foundations or shafting or roofs etc. immediately inspection of the undersigned by arranged to check the stability and safety of the building.
- D. This building can be safety occupied for normal use upto (Indicate year upto which it can be used) 310312021.

year 2020-21)

INT

Sub Division Engineer. Construction Sub Division Jagraon at Ludhian SUB DIVISIONAL ENGINEER PWD B&R BRANCH